


# **AERO-MARINE TECHNOLOGIES, INC.**

*When Service and Experience Matter*



## Did You Know?

The Water Separator is one of the major causes of vacuum generator failure.

This component prevents moisture and other foreign objects from entering the vacuum generator which can lead to premature removal from service and costly repairs due to corrosion and bearing failure.

Standard practice should include the inspection and maintenance of this vital waste system component.

Aero-Marine Technologies specializes in the repair and overhaul of all common vacuum generators including:

606802-2  
14330-375  
14330-350  
J540A4-100  
645172-2

Contact us for a free evaluation of your unit today!

Call 941-205-5420  
or email David Sanders  
david@aeromarinetech.com

**Aero-Marine Technologies**  
**On Time | On Budget | On Wing**

CALL or E-MAIL US TODAY



Shop Hours:  
M-F 8:00 - 5:00

941-205-5420  
[sales@aeromarinetech.com](mailto:sales@aeromarinetech.com)

[WWW.AEROMARINETECH.COM](http://WWW.AEROMARINETECH.COM)  
FAA: 9A5R706B  
EASA: EASA.145.6368

