

AERO-MARINE TECHNOLOGIES, INC.

When Service and Experience Matter



Did You Know?

The 645172-2 Vacuum Generator was once an alternate to the now very popular 606802-2.

While it is recommended that this unit be replaced with the 606802-2, today there are still many in service that require maintenance and overhaul. The most Common issue with the 645172-2 is corrosion on the inlet and outlet adapters.

In addition to the other most common vacuum generators, Aero-Marine Technologies specializes in overhaul of the 645172-2. Send us your units today for a free evaluation.

We Service:

606802-2
14330-375
14330-350
J540A14-100
645172-2

Contact us today!
Call 941-205-5420
or email David Sanders
david@aeromarinetech.com

CALL or E-MAIL US TODAY



Shop Hours:
M-F 8:00 - 5:00

941-205-5420
repairs@aeromarinetech.com

WWW.AEROMARINETECH.COM
FAA: 9A5R706B
EASA: EASA.145.6368

